BMP INSTALLS LTD. INSPECTION REPORT

Job:		Rain in Last 24 hrs (mm)	0
Inspection Date:		Rain in Last Week (mm)	0
Reason for Inspection:	Weekly Inspection	Previous Inspection Date	
Date of Storm Event:	n/a	Weather Forecast	Clear / Warm
Number of Catch Basins Inspected:	54	Activities on Site	

Location	Condition		Sediment Buildup		Action	Date Action Completed	Initials
CB#	Donut	Sock	Depth (cm)	Needs Removal			
1	1	1	<1	No	Needs Removal	n/a	
2	1	4*	1-2	No	Needs Removal	n/a	
3	1	1	0	No	n/a	n/a	
4	1	1	2-3	No	Needs Removal	n/a	
6	1	1	0	No	n/a	n/a	
7	1	1	0	No	n/a	n/a	
8	1	1	0	No	n/a	n/a	
9	1	1	0	No	n/a	n/a	
10	1	Manhole	0	No	n/a	n/a	
12	1	Manhole	0	No	n/a	n/a	
13	1	1	0	No	n/a	n/a	
14	1	1	0	No	n/a	n/a	
15	1	1	0	No	n/a	n/a	
16	1	1	0	No	Needs Removal	n/a	
17	1	1	2-3	Yes	Needs Removal	TBD	
18	1	1	2-3	Yes	Needs Removal	TBD	
19	1	1	0	No	n/a	n/a	
20	1	1	2-3	Yes	Needs Removal	TBD	

Notes / Comments	* CB 2 - Sock ripped off - must have pooled into lane
Recommendations	Leave sock off until it is needed
Inspector's Name	Bill Lindemulder - BMP INSTALLS LTD.
Inspector's Signature	

Condition Legend

1 - Good Condition

2 - Damaged but functioning

3 - Slightly Flattened but functioning

4 - Needs Replacing

PDF Created with deskPDF PDF Writer - Trial :: http://www.docudesk.com

BMP INSTALLS LTD. INSPECTION REPORT

Job:		Rain in Last 24 hrs (mm)	0
Inspection Date:		Rain in Last Week (mm)	0
Reason for Inspection:	Weekly Inspection	Previous Inspection Date	
Date of Storm Event:	n/a	Weather Forecast	Clear / Warm
Number of Catch Basins Inspected:	54	Activities on Site	

Location	Condition		Sediment Buildup		Action	Date Action Completed	Initials
CB#	Donut	Sock	Depth (cm)	Needs Removal			
21	1	1	3-4	Yes	Protection Removal	TBD	
22	1	1	1-2	No	n/a	n/a	
23	1	Manhole	0	No	n/a	n/a	
24	Abandoned	Abandoned					
25	1	1	1-2	Yes	None	TBD	
26	1	Not Present	0	No	n/a	n/a	
27							
28							
29	1	3	1-2	No	n/a	n/a	
30	1	3	1-2	No	n/a	n/a	
31	Abandoned						
32	Abandoned						
33	Abandoned						
34	1	1	0	No	n/a	n/a	
35	1	1	0	No	n/a	n/a	
36	Not Installed				CB Full of Sediment	n/a	
37	1	1	5-6	Yes	Needs Removal	TBD	
38	1	1	5-6	Yes	Needs Removal	TBD	
39	1	1	3-4	Yes	Needs Removal	TBD	
40	1	1	3-4	Yes	Needs Removal	TBD	

Notes / Comments	
Recommendations	
Inspector's Name	Bill Lindemulder - BMP INSTALLS LTD.
Inspector's Signature	

Condition Legend

1 - Good Condition

2 - Damaged but functioning

3 - Slightly Flattened but functioning

4 - Needs Replacing

PDF Created with deskPDF PDF Writer - Trial :: http://www.docudesk.com

BMP INSTALLS LTD. INSPECTION REPORT

Job:		Rain in Last 24 hrs (mm)	0
Inspection Date:		Rain in Last Week (mm)	0
Reason for Inspection:	Weekly Inspection	Previous Inspection Date	
Date of Storm Event:	n/a	Weather Forecast	Clear / Warm
Number of Catch Basins Inspected:	54	Activities on Site	

Location	Condition		Sediment Buildup		Action	Date Action Completed	Initials
CB#	Donut	Sock	Depth (cm)	Needs Removal			
41	1	4*	0	No	n/a	n/a	
42	1	1	0	No	n/a	n/a	
43	Abandoned						
44	1	1	0	No	n/a	n/a	
45	1	3	1-2	No	n/a	n/a	
46	1	1	0	No	n/a	n/a	
47	1	1	0	No	n/a	n/a	
48	1	1	0	No	n/a	n/a	
49	1	1	0	No	n/a	n/a	
50	1	1	0	No	n/a	n/a	
51	1	1	0	No	n/a	n/a	
52	1	1	0	No	n/a	n/a	
53	1	1	0	No	n/a	n/a	
54	1	1	0	No	n/a	n/a	
55	1	1	0	No	n/a	n/a	
56	1	1	0	No	n/a	n/a	
57	1	1	0	No	n/a	n/a	
58	1	1	0	No	n/a	n/a	
59	1	1	0	No	n/a	n/a	
60	1	1	0	No	n/a	n/a	

Notes / Comments	* CB 41 - Sock ripped off - must have pooled into lane
Recommendations	Leave sock off until it is needed
Inspector's Name	Bill Lindemulder - BMP INSTALLS LTD.
Inspector's Signature	

Condition Legend

1 - Good Condition

2 - Damaged but functioning

3 - Slightly Flattened but functioning

4 - Needs Replacing

PDF Created with deskPDF PDF Writer - Trial :: http://www.docudesk.com

BMP INSTALLS LTD. INSPECTION REPORT

Job:		Rain in Last 24 hrs (mm)	0
Inspection Date:		Rain in Last Week (mm)	0
Reason for Inspection:	Weekly Inspection	Previous Inspection Date	
Date of Storm Event:	n/a	Weather Forecast	Clear / Warm
Number of Catch Basins Inspected:	54	Activities on Site	

Location	Condition		Sediment Buildup		Action	Date Action Completed	Initials
CB#	Donut	Sock	Depth (cm)	Needs Removal			
61	1	1	0	No	n/a	n/a	
62	1	1	0	No	n/a	n/a	
63	0	0	0		Needs Install	TBD	
64	0	0	0		Needs Install	TBD	

Notes / Comments	
Recommendations	
Inspector's Name	Bill Lindemulder - BMP INSTALLS LTD.
Inspector's Signature	

Condition Legend

1 - Good Condition

2 - Damaged but functioning

3 - Slightly Flattened but functioning

4 - Needs Replacing

PDF Created with deskPDF PDF Writer - Trial :: http://www.docudesk.com