

BMP INSTALLS LTD. - Erosion and Sediment Inspection / Maintenance Log

Job #		Construction Activities	
City Project #		Current Weather	Cool / Clear
Site Location		Weather Forecast	Clear / Warm
Contractor(s) On Site		Rain in Last 24hrs (mm)	0
Heavy Equipment On Site		Rain in Last Week (mm)	0
Inspection Date		Previous Inspection Date	

Preventive Measure	Location	Condition	General Performance	Sediment Level	Action Required	Date Action Completed	Initials
Silt Fence		Good	Working	*	none		
Silt Fence		Very Good	Working	0	none		
Silt Fence		Removed	n/a	n/a			
Dust Controls		Very Good	Working	n/a	none		
Storm Inlet		Very Good	Working	0	none		
Safety Fence		Very Good	Working	n/a	none		
Safety Fence		Good	Working	n/a	none		
Safety Fence		Good	Working	n/a	none		
Safety Fence		Very Good	Working	n/a	none		
Catch Basins	refer to BMP INSTALLS CATCH BASIN INSPECTION REPORT						
Silt Fence		Very Good	Working	0	none		
Storm Inlet		Very Good	Working	0	none		
Storm Inlet		Very Good	Working	0	none		
Storm Inlet 2		Very Good	Working	0	none		

Notes / Comments	* Stock pile has been leveled and pushed against silt fence
Recommendations	Keep a close eye on fence as some may need replacing if it fails
Inspector's Name	Bill Lindemulder - BMP INSTALLS LTD.

Inspector's Signature